

MATERIAL SAFETY DATA SHEET

1. Product and Company Identification

087 **Product number**

Product name Fast Tack 87 General Purpose Mist Adhesive

Effective date 17-Apr-2008 Company information Sprayway, Inc. 484 Vista Ave.

Addison, IL 60101 United States

Company phone General Assistance 630-543-7600

Emergency telephone US 800-424-9300 703-527-3887 **Emergency telephone outside US**

Version # 04

28-Feb-2008 Supersedes date

2. Hazards Identification

EXTREMELY FLAMMABLE **Emergency overview**

CONTENTS UNDER PRESSURE.

Aerosol. Pressurized container may explode when exposed to heat or flame.

Harmful in contact with eyes. Prolonged exposure may cause chronic effects.

This product is considered hazardous under 29 CFR 1910.1200 (Hazard **OSHA** regulatory status

Communication).

Potential health effects

Eyes Contact may irritate or burn eyes. Eye contact may result in corneal injury.

Skin Prolonged or repeated contact can result in defatting and drying of the skin which may

result in skin irritation and dermatitis (rash).

Inhalation Intentional misuse by concentrating and inhaling the product can be harmful or fatal.

Prolonged inhalation may be harmful.

Ingestion Exposure by ingestion of an aerosol is unlikely. Ingestion may cause gastrointestinal

irritation, nausea, vomiting and diarrhea. May cause delayed lung damage.

Target organs Central nervous system. Respiratory system.

Chronic effects Conjunctiva. May cause central nervous system disorder (e.g., narcosis involving a loss

of coordination, weakness, fatigue, mental confusion, and blurred vision) and/or damage.

May cause delayed lung damage.

Signs and symptoms Discomfort in the chest. Corneal damage. Narcosis. Conjunctivitis. Defatting of the skin.

Irritation.

Potential environmental effects Components of this product are hazardous to aquatic life.

3. Composition / Information on Ingredients

Components	CAS#	Percent
Acetone	67-64-1	15 - 20
n-Hexane	110-54-3	15 - 20
Dimethyl Ether	115-10-6	10 - 15
n-Butane	106-97-8	8 - 10
Cyclohexane	110-82-7	8 - 10
Isobutane	75-28-5	5 - 8
Propane	74-98-6	5 - 8

10 - 20 Non-hazardous and other components below reportable levels

trade name Fast Tack 87 General Purpose Mist Adhesive MSDS US 1/5

4. First Aid Measures

First aid procedures

Eye contact Immediately flush eyes with plenty of water for at least 15 minutes. Remove contact

lenses, if present and easy to do. Get medical attention immediately.

Skin contact Immediately take off all contaminated clothing. Wash off with warm water and soap. Get

medical attention if irritation develops or persists.

Inhalation Move to fresh air. Call a physician if symptoms develop or persist.

Ingestion Rinse mouth. Do not induce vomiting without medical advice. If vomiting occurs naturally, have victim lean forward to reduce risk of aspiration. Do not use mouth-to-mouth method

if victim ingested the substance. Induce artificial respiration with the aid of a pocket mask

equipped with a one-way valve or other proper respiratory medical device.

Notes to physician Symptoms may be delayed.

General advice Call a physician if symptoms develop or persist.

5. Fire Fighting Measures

Containers may explode when heated. Vapor or gas may spread to distant ignition Flammable properties

sources and flash back.

Extinguishing media

Suitable extinguishing media

Unsuitable extinguishing media

Protection of firefighters

Protective equipment and precautions for firefighters

Foam. Alcohol foam. Dry chemical. Carbon dioxide (CO2). Halons. Do not use a solid water stream as it may scatter and spread fire.

In the event of fire and/or explosion do not breathe fumes. Wear full protective clothing, including helmet, self-contained positive pressure or pressure demand breathing apparatus, protective clothing and face mask. Containers should be cooled with water to prevent vapor pressure build up. For massive fire, use unmanned hose holders or monitor nozzles; if this is impossible, withdraw from area and let fire burn.

6. Accidental Release Measures

Do not touch damaged containers or spilled material unless wearing appropriate Personal precautions

protective clothing. Ventilate closed spaces before entering. Keep unnecessary personnel

Methods for containment Eliminate all ignition sources (no smoking, flares, sparks, or flames in immediate area).

Stop leak if you can do so without risk. Move the cylinder to a safe and open area if the

leak is irreparable.

Methods for cleaning up Should not be released into the environment.

Small Spills: Wipe up with absorbent material (e.g. cloth, fleece). Clean contaminated

surface thoroughly.

7. Handling and Storage

Handling Pressurized container: Do not pierce or burn, even after use. Do not handle or store near

an open flame, heat or other sources of ignition. Use only in area provided with

appropriate exhaust ventilation. Do not use if spray button is missing or defective. Do not get this material in contact with eyes. Do not get this material in contact with skin. Avoid

prolonged exposure.

Storage Level 3 Aerosol.

> Contents under pressure. Do not puncture, incinerate or crush. The pressure in sealed containers can increase under the influence of heat. Avoid exposure to long periods of sunlight. Keep in an area equipped with sprinklers. Keep out of the reach of children. Use

care in handling/storage.

MSDS US 2/5 Revision date: 17-APR-2008 Print date: 17-APR-2008 Product #: 087

8. Exposure Controls / Personal Protection

Exposure limits

AC	G	IH.
	_	

Components	CAS#	TWA	STEL	Ceiling
Acetone	67-64-1	500 ppm	750 ppm	Not established
n-Hexane	110-54-3	50 ppm	1000 ppm	Not established
n-Butane	106-97-8	1000 ppm	Not established	Not established
Cyclohexane	110-82-7	100 ppm	Not established	Not established
Isobutane	75-28-5	1000 ppm	Not established	Not established
Propane	74-98-6	1000 ppm	Not established	Not established

OSHA

Components	CAS#	TWA	STEL	Ceiling
Acetone	67-64-1	1000 ppm	Not established	Not established
n-Hexane	110-54-3	500 ppm	Not established	Not established
Cyclohexane	110-82-7	300 ppm	Not established	Not established
Propane	74-98-6	1000 ppm	Not established	Not established

Engineering controls

Use process enclosures, local exhaust ventilation, or other engineering controls to control

airborne levels below recommended exposure limits.

Personal protective equipment

Eye / face protection Wear chemical goggles. **Skin protection** Protective gloves.

Respiratory protection When workers are facing concentrations above the exposure limit they must use

appropriate certified respirators.

General hygeine considerations Do not get this material in contact with eyes. Do not get this material in contact with skin.

Handle in accordance with good industrial hygiene and safety practice.

9. Physical & Chemical Properties

Appearance Compressed liquefied gas. **Boiling point** 69.8 °F (21.1 °C) estimated

Color Tan.

Flammability (HOC) 41.8016 kJ/g estimated

Flash back Yes

Flash point -156 °F (-104.4 °C) estimated

Form Aerosol.

Odor Solvent.

pH Not applicable

Physical state Liquid.

Pressure 46 - 56 psig @ 70F

Solubility None

Specific gravity 0.7069 estimated

10. Chemical Stability & Reactivity Information

Chemical stability Risk of ignition.

Conditions to avoid Heat, flames and sparks.

Hazardous decomposition products May include oxides of oxides of carbon.

11. Toxicological Information

Acute effects Acute LD50: 8571 mg/kg estimated, Rat, Dermal

Acute LC50: 101 mg/l/4h estimated, Rat, Inhalation

Local effects Contact may irritate or burn eyes. Components of the product may be absorbed into the

body through the skin.

trade_name Fast Tack 87 General Purpose Mist Adhesive MSDS US
Product #: 087 Revision date: 17-APR-2008 Print date: 17-APR-2008 3 / 5

Chronic effects Hazardous by OSHA criteria. Repeated absorption may cause disorder of central nervous

system, liver, kidneys and blood. Prolonged or repeated exposure may cause lung injury.

Prolonged exposure may cause chronic effects.

Further information Symptoms may be delayed.

12. Ecological Information

Ecotoxicity LC50 15.77 mg/L estimated, Fish, 96.00 Hours,

EC50 66843 mg/L estimated, Daphnia, 48.00 Hours,

IC50 5138 mg/L estimated, Algae, 72.00 Hours,

Environmental effects Harmful to aquatic life.

13. Disposal Considerations

Waste codes D001: Waste Flammable material with a flash point <140 F

Disposal instructions Contents under pressure. Dispose of this material and its container at hazardous or special waste collection point. Incinerate the material under controlled conditions in an

approved incinerator. Do not allow this material to drain into sewers/water supplies. If discarded, this product is considered a RCRA ignitable waste, D001. Dispose in

accordance with all applicable regulations.

14. Transport Information

Department of Transportation (DOT) Requirements

Basic shipping requirements:

Proper shipping name Consumer commodity

ORM-D **Hazard class** Subsidiary hazard class None

Additional information:

Packaging exceptions 156, 306 156, 306 Packaging non bulk Packaging bulk None

IMDG

Basic shipping requirements:

Proper shipping name AEROSOLS, flammable

Hazard class 2.1 **UN** number 1950

Additional information:

Packaging exceptions LTD QTY 5F Labels required None **Transport Category** 2

IATA

Basic shipping requirements:

Aerosols, flammable Proper shipping name

Hazard class 2 1 **UN number** 1950

Additional information:

Packaging exceptions LTD QTY Labels required None





15. Regulatory Information

US federal regulations This product is a "Hazardous Chemical" as defined by the OSHA Hazard Communication

Standard, 29 CFR 1910.1200.

All components are on the U.S. EPA TSCA Inventory List.

U.S. - CERCLA/SARA - Section 313 - Emission Reporting

110-82-7 Cyclohexane 1.0 % de minimis concentration n-Hexane 110-54-3 1.0 % de minimis concentration

MSDS US 4/5 Revision date: 17-APR-2008 Print date: 17-APR-2008 Product #: 087

Occupational Safety and Health Administration (OSHA)

29 CFR 1910.1200 hazardous

chemical

CERCLA (Superfund) reportable quantity

Acetone: 5000.0000 n-Hexane: 5000.0000 Cyclohexane: 1000.0000

Superfund Amendments and Reauthorization Act of 1986 (SARA)

Hazard categories Immediate Hazard - Yes

Delayed Hazard - Yes Fire Hazard - Yes Pressure Hazard - Yes Reactivity Hazard - No

Section 302 extremely

hazardous substance

Section 311 hazardous chemical Yes

Inventory status

Country(s) or region	Inventory name	On inventory (yes/no)*
China	Inventory of Existing Chemical Substances in China (IECSC)	No
Europe	European Inventory of New and Existing Chemicals (EINECS)	No
Europe	European List of Notified Chemical Substances (ELINCS)	No
Japan	Inventory of Existing and New Chemical Substances (ENCS)	No
Korea	Existing Chemicals List (ECL)	No
United States & Puerto Rico	Toxic Substances Control Act (TSCA) Inventory	Yes

A "Yes" indicates that all components of this product comply with the inventory requirements administered by the governing country(s)

State regulations

U.S. - Pennsylvania - RTK (Right to Know) List

67-64-1 **Environmental hazard** Acetone 110-82-7 Environmental hazard Cyclohexane

Dimethyl Ether 115-10-6 Present Isobutane 75-28-5 Present n-Butane 106-97-8 Present Present n-Hexane 110-54-3 Propane 74-98-6 Present

16. Other Information

HMIS® ratings Health: 1*

Flammability: 4 Physical hazard: 0

Prepared by Regulatory Compliance

The information provided in this Safety Data Sheet is correct to the best of our **Disclaimer**

> knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified

in the text.

Issue date 17-Apr-2008

Physical & Chemical Properties: Physical & Chemical Properties MSDS sections updated

Transport Information: Product Shipping Name/Packing Group

MSDS US 5/5 Revision date: 17-APR-2008 Print date: 17-APR-2008 Product #: 087